

SERVICE NOTE

Date: 18 May 2011

Subject:


- Wear on hoses of water cooling system in the rear fairing.

Aircraft concerned:

- All versions of the arv Tanarg trike and especially version ES.

To be checked:

Inspect the water hoses thoroughly and protect areas of contact to avoid wear. Inspect particularly the area near the inside of the rear fairing (output of water radiator).



Hoses to be inspected